

	Handschuhe gibt oder sie unter extremen Bedingungen verwendet werden. Die Handschuhe dürfen nicht weiter verwendet werden, wenn die Sichtprüfung oder die elektr. Prüfung nicht bestanden wurde.
Während der Benutzung	Handschuhe aus Naturkautschuk können Inhaltsstoffe enthalten, die eine mögliche Ursache von Allergien bei sensiblen Personen sein können. Sollte eine allergische Reaktion auftreten, sollte sofort ärztlicher Rat eingeholt werden. Falls der Isolierhandschuh ohne Lederschutzhandschuh verwendet wird, ist äußerste Vorsicht vor mechanischen Beanspruchungen geboten (Durchstichen, Abschürfungen oder andere Schäden). Stellen Sie sicher, dass zwischen dem Ende der Stulpe des Schutzhandschuhs und der Stulpe des Gummihandschuhs ein ausreichender Abstand vorhanden ist. Es wird empfohlen, dass der Gummihandschuh der Klasse 0 und OO mindestens 1,3 cm Zoll über das Ende des Schutzhandschuhs hinausragt, 2,6 Zoll bei Klasse 1, 5,2 cm Zoll bei Klasse 2, 7,8 cm Zoll bei Klasse 3.
Reinigung	Die Handschuhe müssen mit einer milden Seife gewaschen und gründlich mit klarem Wasser ab gespült werden. Die Trocknung darf nicht bei direktem Sonnenlicht oder anderen Wärmequellen erfolgen → Lufttrocknung. Wenn die Handschuhe zu irgendeinem Zeitpunkt mit Produkten auf Erdölbasis oder organischen Lösungsmitteln (Öle, Fette, Benzin, Hydraulikflüssigkeit) in Kontakt kommen, Handcremes und -pasten) sollten sie sofort gewaschen und vor der Wiederverwendung einem Labortest unterzogen werden.
Lagerung	Die Handschuhe dürfen nicht gefaltet, geknickt oder einer ähnlichen Belastung ausgesetzt werden, die zu einer Dehnung oder Stauchung des Materials führen kann. Sie dürfen nicht auf links gedreht (umgedreht) gelagert werden. Die Handschuhe müssen bei Nichtgebrauch in ihrer originalen Schutztasche aufbewahrt und transportiert werden. Sie dürfen keiner Wärmestrahlung einer direkten Wärmequelle ausgesetzt werden. Sie müssen von Chemikalien, Ölen, Lösungsmitteln, gefährlichen Dämpfen, Rauch oder elektrischen Entladungen ferngehalten werden. Die maximale Umgebungstemperatur darf 40°C nicht überschreiten; Feuchtigkeit, direktes Sonnenlicht und Ozonquellen sind bei der Lagerung auszuschließen. Handschuhe der Klassen 1, 2, 3 und 4 dürfen dann erstmalig verwendet werden, wenn die letzte elektrische Prüfung nicht länger als 12 Monate zurückliegt.
Hersteller	Dipped Products PLC 400 Deans Road, Colombo 10, Sri Lanka
Zertifizierung	SATRA Technolgy Europe Limited, Bracetown Business Park, Clonee, D15 YN2P, Ireland (notified body number 2777) Konformitätserklärung: www.bsd-dresden.de/ppe
Produktkontrolle	SGS Fimko Oy, Takomotie 8, FI-00380 Helsinki, Finland (notified body number 0598)
Distributor	BSD Bildungs- und Servicezentrum GmbH Lutherstraße 33 D - 01900 Großbröhnsdorf Tel. +49 35952/410-0 www.bsd-dresden.de

DIPPED PRODUCTS PLC

400, DEANS ROAD, COLOMBO 10, SRI LANKA.

EC REPRESENTATIVE

ICOQUANTI S.p.A
Corso Carbonara 10A/1
16125 Genoa
Italy
Phone : 00 39 010 218298
Fax : 00 39 010 2724051
E-mail : assistenza@icoguantii.it

CERTIFICATION BODY

SATRA Technology Europe Limited,
Bracetown Business Park,
Clonee,
D15 YN2P, Ireland. (notified body number 2777)
Tel: +441536410000

USER INFORMATION

Glove Designation : LINEPRO 61MC
Glove Description : Natural rubber electrical insulation gloves

These gloves are intended to be used exclusively for electrical purposes

The product is classed as Category III of Personal Protective Equipment (PPE) by the European PPE regulation EU 2016/425 and have been shown to comply with this Regulation through the Harmonised European Standard(s) such as EN 60903:2003 and IEC 60903:2014.

1. **Sizes available** : 7, 7.5, 8, 8.5, 9, 9.5, 10, 10.5, 11, 11.5, 12

2. **Comfort and Efficiency**

Length of glove - Conforms to EN 60903:2003
Hand fit - Conforms to EN 60903:2003

3. **Protection against Electrical Shocks according to EN60903:2003 & IEC 60903:2014**

DPL
LINEPRO

Electricians Gloves

Manufactured and tested in accordance with
EN 60903:2003 & IEC 60903:2014 standards

CE 0598



GS-ET-42-1:2019-02, electrically insulating gloves with additional protection against the thermal effect of electrical fault arc

GS-ET-42-1:2019-02



APC 2

Categories

Category	Resistant to
A	Acid
H	Oil
Z	Ozone
R	Acid, Oil, Ozone
C	Extremely Low Temperature

Glove Category	Resistant to
Class 00	A, C, Z
Class 0	A, C, Z
Class 1	R, C
Class 2	R, C
Class 3	R, C
Class 4	R, C

Glove Class	ATPV Value	APC Value
Class 00	8,4 cal/cm ²	APC 1
Class 0	8,5 cal/cm ²	APC 2
Class 1	10,6 cal/cm ²	APC 2
Class 2	21,0 cal/cm ²	APC 2
Class 3	40,5 cal/cm ²	APC 2
Class 4	36,2 cal/cm ²	APC 2

Table: Designation of maximum use of voltage

Category	Class	Length	Colour	Cuff	Maximum Use Voltage (Volts) AC	Maximum Use Voltage (Volts) DC
Low Voltage	00	28 cm / 36 cm	Red/Black	ST	500	750
	0	28 cm/ 36 cm/41 cm /46 cm	Red/Black	ST	1,000	1,500
High Voltage	1	36 cm/ 41 cm/ 46 cm	Red/Black	ST	7,500	11,250
	2	36 cm/ 41 cm/ 46 cm	Red/Black	ST	17,000	25,500
	3	36 cm/ 41 cm/ 46 cm	Red/Black	ST	26,500	39,750
	4	41 cm/ 46 cm	Red/Black	ST	36,000	54,000

The maximum use voltage is the A.C. voltage rating of the protective equipment that designates the maximum nominal voltage of the energized system that may be safely worked. The nominal voltage is equal to the phase-to-phase voltage on multi phase circuits.

If there is multiple exposure in system area, and the system voltage exposure is limited to the phase (polarity on the DC system) to ground potential, the phase (polarity on the DC system) to ground potential, shall be considered to be the nominal voltage.

If electrical equipment and devices are insulated, or isolated, or both, such that the multiple exposure on an earthed, neutral star circuit (grounded wye circuit) is removed and if supplemental insulation (eg, Insulated aerial device or structure-mounted insulating work platform) is used to insulate the worker from ground, then the nominal design voltage may be considered as the phase-to-ground voltage on that circuit.

Instructions for before use

- Gloves should be inspected (surfaces - inside and outside), daily or more often if used without leather protectors.
- Rings, watches, jewelry or sharp objects on hands or arms should not be worn while wearing the gloves
- If at any stage the gloves come into contact with petroleum based products or organic solvents (oils, fats, gasoline, hydraulic fluid, hand creams and pastes) they should be immediately washed and submitted for laboratory testing before reuse
- If protective gloves other than rubber gloves are used together with this product, they must be worn over the rubber gloves
- Leather protectors and the rubber gloves must be inspected together at the same time
- The guidelines for the protector's inspection should be followed paying particular attention to : metal particles, any snagged wires or any other material that could abrade or compromise integrity of the gloves
- Check for any physical damage: abrasion marks, cracks, holes, nicks, tear, puncture, depressions, soft spots, stickiness, discoloration or any other blemishes
- The gloves should be inflated, by sealing the cuff and rolling the glove over the seal
- Pressure need be applied to different areas of the glove
- A visual inspection should be carried out again, paying attention also to any escaping air
- The gloves and sleeves should be tested electrically in accordance with local statutes or at a minimum of once every 6 and 12 months respectively
- If there is any doubt whatsoever about the condition of the gloves, or they are being used under extreme conditions, then gloves should be submitted for laboratory testing before reuse
- Destroy the glove if any visual or physical abnormalities are found
- All inspections and tests should be conducted as per recommendations in:
 - ASTM F 496 (Specification for In-Service Care of Insulating Gloves and Sleeves)
 - ASTM F1236 (Guide for Visual Inspection of Electrical Protective Rubber Products)

Precautions during use

- Gloves containing natural rubber latex might contain ingredients which are known to be a possible cause of allergies in sensitized persons. If any allergic reaction should occur then medical advice should be obtained immediately.
- Always use the rubber insulating gloves in the intended voltage class
- The voltage class can be found on the label, on the box, bag and glove itself
- Leather protectors should always be worn over rubber insulating gloves to protect the gloves from physical damage
- If necessary to use the rubber insulating glove without a leather protector; extreme care should be taken against punctures, abrasions or other damage. If a leather protector is not used, it is essential to wear gloves at least one voltage class higher than normally necessary for all classes higher than 0
- Ensure sufficient flash over cover between the end of the protector's and rubber glove's cuffs. It is recommended that the glove should extend past the end of the protector by a minimum of 1/2 inch for class 0 and 00, 1 inch for class 1, 2 inches for class 2, 3 inches for class 3 and 4 inches for class 4

Cleaning

- Gloves must be washed with a mild soap, rinsed thoroughly with clean water, air dried away from direct-sunlight or sources of heat
- If at any stage the gloves come into contact with petroleum based products or organic solvents (oils, fats, gasoline, hydraulic fluid, hand creams and pastes) they should be immediately washed and submitted for laboratory testing before reuse

Storage Gloves must;

- Never be folded, wrinkled or exposed to any stress that may cause them to lengthen or shrink (the strain on rubber at a folded point is equal to stretching the glove to twice its length)
- Never be stored inside out. Storing gloves reversed strain the rubber severely and causes ozone cutting
- Be stored in their protective bag when not in use
- Be away from direct irradiation of any heat source
- Be kept away from chemicals, oils, solvents, hazardous vapours, smoke or electrical discharge
- Stored where ambient temperature is not above 40 C
- Be stored away from: moisture, direct-sunlight, direct-light and source of ozone
- Recommend to use the original packaging for transportation

The gloves can be issued to service before completing twelve months from the date of manufacture without testing and once issued for service, gloves will need to be retested every six months thereafter. If the gloves have not been used within one year from the date of manufacture, the user can still use it after conducting a dielectric test and assuring that the gloves still provide adequate protection according to the standard IEC 60903:2014.

The product is manufactured under a Quality Control System which has been satisfactorily assessed by SGS Fimko Oy (Notified Body number 0598) Takomotie 8, FI-00380 Helsinki, Finland

As meeting the requirement of PPE Regulation (EU) 2016/425 Module D.

Note - You can obtain the declaration of conformity through www.dplgroup.com

Benutzerinformation

Isolierende Handschuhe Klasse 00, 0, 1, 2, 3
nach EN 60903:2003 und IEC 60903:2014
GS-ET-42-1: APC 1 (KI. 00); APC 2 (KI. 0)
(03/2024)



BSD-Artikelnummer:
Klasse 00: 74320xx
Klasse 0: 74310xx
Klasse 1: 74320xx
Klasse 2: 74310xx
Klasse 3: 74320xx

Produkt: LINEPRO 61MC, isolierender Naturkautschuk-Handschuh nur für elektrotechnische Anwendungen mit zusätzlichem Störlichtbogenschutz nach GS-ET-42-1

Konformität: Der isolierende Handschuh ist gemäß der EU-PSA-Verordnung 2016/425 PSA (Persönliche Schutzausrüstung) der Kategorie III und ist konform mit der EU-PSA-Verordnung durch Anwendung der harmonisierten Norm EN 60903:2003 und IEC 60903:2014.

Größen: 8, 9, 10, 11

Kennzeichnung und Kategorie:

Spannungsklasse	Kategorie	Länge	Maximaler Nennspannungs-Anwendungsbereich	
Klasse 00 (Class 00)	A, C, Z	36 cm	500 V AC / 750 V DC	APC 1
Klasse 0 (Class 0)	A, C, Z	36 cm	1000 V AC / 1500 V DC	APC 2
Klasse 1	R, C	36 cm / 41 cm	7.500 V AC / 11.250 V DC	APC 2
Klasse 2	R, C	36 cm / 41 cm	17.000 V AC / 25.500 V DC	APC 2
Klasse 3	R, C	36 cm / 41 cm	26.500 V AC / 39.750 V DC	APC 2

Kategorie A: Beständigkeit gegen Säure (Category A)
Kategorie C: Beständigkeit gegen extrem niedrige Temperaturen (Category C)
Kategorie R: Beständigkeit gegen Säure, Öl, Ozon (Category R)
Kategorie Z: Beständigkeit gegen Ozon (Category Z)

Sicherheits-hinweise
Die Maximalspannung der Anlagen, an denen die Handschuhe angewendet werden dürfen, ist begrenzt durch die Spannungsklasse der Handschuhe, die auf den Handschuhen und den Handschuhverpackungen markiert ist. Sie entspricht der Leiter-Leiter-Spannung bei 3-Phasen-Systemen bzw. der Spannung zwischen zwei Potenzialen bei Einphasensystemen oder DC-Anwendungen.

Vor der Benutzung
Die Handschuhe müssen vor und nach der Benutzung einer Sichtprüfung (Oberflächen – innen und außen) unterzogen werden. Prüfen Sie sie auf physische Schäden wie z.B. Abriebspuren, Risse, Löcher, Kerben, Einstiche, Vertiefungen, weiche Stellen, Klebrigkeit, Verfärbung oder andere Makel. | Durch Einrollen der Stulpe müssen die Handschuhe vor und nach der Benutzung aufgeblasen werden, um dadurch einen Innendruck zu erzeugen. Damit können Undichtigkeiten (Löcher, Risse) der Handschuhe aufgrund austretender Luft festgestellt werden. | Ringe, Uhren, Schmuck oder scharfe Gegenstände an Händen oder Armen dürfen beim Benutzen der Handschuhe nicht getragen werden! | Wenn die Handschuhe zu irgendeinem Zeitpunkt mit Produkten auf Erdölbasis oder organischen Lösungsmitteln (Öle, Fette, Benzin, Hydraulikflüssigkeit, Handcremes und -pasten) in Kontakt kommen, sollten sie sofort gewaschen und vor der Wiederverwendung einem Labortest unterzogen werden. | Werden Lederschutzhandschuhe benötigt, müssen sie über den Gummihandschuhen getragen werden. Die Schutzhandschuhe müssen vor der Benutzung auch auf Verunreinigungen (z.B. Metallpartikel, Drahtreste) geprüft werden, die den Gummihandschuh beschädigen könnten. | Die Handschuhe sollten in Übereinstimmung mit den nationalen Vorschriften und Regeln regelmäßig elektrisch geprüft werden und darüber hinaus auch dann, wenn es irgendwelche Zweifel über den Zustand der